### RUDDER & WRENCH

Savvy Maintenance coverage sponsored by AIRCRAFT SPRUCE



#### SAVVY MAINTENANCE / OPINION

# **Grading On the CURVE** You can learn a lot from your airplane's report card

**BY MIKE BUSCH** 

JACK OWNS A 2016 Cirrus SR22 with a Garmin Perspective glass cockpit—basically a G1000 on steroids. His multifunction display records tons of data on an SD card—cylinder head temperature (CHT), exhaust gas temperature, oil pressure and temperature, manifold absolute pressure, rpm, fuel flow, altitude, true airspeed, electrical bus voltages and current, even GPS coordinates—and Jack regularly uploads this data to my company's SavvyAnalysis platform.

Once uploaded, Jack's data is automatically scanned by a sophisticated machine-learning algorithm for evidence of failing exhaust valves. Whenever Jack requests it, selected flights are scrutinized by Savvy's team of professional data analysts who prepare a comprehensive report on the health of Jack's engine and the appropriateness of his powerplant management procedures.

In addition, Jack receives regular report cards that graphically show how his SR22 stacks up when compared to a cohort of more than 1,500 other normally aspirated Cirrus SR22s that are followed by SavvyAnalysis. Jack's report cards display numerous parameters related to performance, efficiency, longevity, and health of his aircraft and its engine, and essentially grades them on the curve to show Jack how his aircraft is stacking up when compared to the other aircraft in his cohort.

#### How am I doing?

In late 2020, Jack was reviewing his most recent report card. Its first section focused on the cruise phase of his flights:

SR22 Normally Aspirated • IO-550 • Includes 19 flights between Oct 11, 2019 and Oct 10, 2020, compared with 128829 flights by a cohort of 1504 SR22 Normally Aspirated aircraft.							
	OWER IN CRUISE	011 01 1304 SIGE 1401	many copirated t				
Measures you	ar engine's power or	aput during chuise flight. I fuel efficiency, elevated					
0%	25%	50%	75%	100%			
49.5		63.9	1.000	1			
45%Pwr	57.7%Pwr	62.2%Pwr	66.6%Pwr	90%Pwr			
ALTITUDE I	buting to longer than N CRUISE (MSL)	er output duning cruise fl in average cylinder life, cruise phase of flight, For	-				
altrudes gena	erally provide better	performance and efficient	nçy.				
0%	25%	50%	75%	100%			
		0.000	11500	Terrer			
2000 ft							
	5230 R	7190 ft	9040 ft	19500 ft			
SAVVY SAYS Your cruising SPEED IN CI We use TAS if output, result	albitudes tend to be RUISE (K.) available, otherwise ting in high CHT and	7190 ft high: resulting in good fu e ground speed. Higher s reduced cylinder life. Or	uel efficiency and p	erformance. to high powe			
SAVVY SAYS Your cruising SPEED IN CO We use TAS if nore efficient	albitudes tend to be RUISE (K.) available, otherwise ong in high CHT and t albitudes.	high, resulting in good fu e ground speed. Higher si reduced cylinder life. Or	uel efficiency and p peed might be due possibly operation	erformance. to high power at higher.			
SAVVY SAYS Your cruising SPEED IN CI We use TAS if output, result	albitudes tend to be RUISE (K.) available, otherwise ting in high CHT and	high, resulting in good fu	uel efficiency and pr peed might be due possibly operation 75%	erformance. to high powe			
SAWY SAYS Your cruising SPEED IN CI We use TAS If output, result more efficient 0%	Altitudes tend to be RUISE (K.) available, otherwise ong in high CHT and t altitudes. 25%	high, resulting in good fu e ground speed. Higher s reduced cylinder life, Or 50%	uel efficiency and p peed might be due possibly operation 75%	erformance. to high power at higher. 100%			
SAVVY SAYS Your cruising SPEED IN CO We use TAS if output, result more efficient 17%	albtudes tend to be RUISE (K.) available, otherwiss ang in high CHT and a albfudes. 25% 156 KTAS	high, resulting in good fu e ground speed. Higher si reduced cylinder life. Or 50%-	uel efficiency and pr peed might be due possibly operation 75%	erformance. to high power at higher.			
SAVVY SAYS Your cruising SPEED IN CO We use TAS Id output, result more efficient 0% 125 KTAS SAVVY SAYS	atotudes tend to be RUISE (K.) available, otherwissi ang in high, ctri and a bitfudes. 25% 25% 25% 25%	high, resulting in good fu e ground speed. Higher s reduced cylinder life, Or 50%	uel efficiency and p peed might be due possibly operation 75% 176 176 171 KTAS	erformance. to high power at higher. 100%			
SAVAY SAYS rour cruising SPEED IN CI We use TAS if output, result more efficient 9% 125 kTAS SAVAY SAYS rour cruise is FUEL EFFICI	albtudes fend to be RUISE (K.) available, otherwise ang in high CHT and t albitudes. 25% 25% 25% 25% 25% 25% 25% 25%	high, resulting in good A e ground speed. Higher a reduced symder life. Or 50% 164 KTAS n compared with your co	uel efficiency and pr peed might be due possibly operation 75% 175 171 KTAS	erformance. to high power at higher. 100%			
SAVAY SAYS rour cruising SPEED IN CI We use TAS if output, result more efficient 9% 125 kTAS SAVAY SAYS rour cruise is FUEL EFFICI	albtudes fend to be RUISE (K.) available, otherwise ang in high CHT and t albitudes. 25% 25% 25% 25% 25% 25% 25% 25%	high: resulting in good A ground speed, Jegher si reduced symder life. Or 50%. 5 164 KTAS In compared with your co ALL)	uel efficiency and pr peed might be due possibly operation 75% 175 171 KTAS	erformance. to high power at higher. 100%			

Jack's conclusion was that his numbers looked pretty darn good. The report card showed that Jack had been operating at relatively modest cruise power settings (50 to 64 percent), primarily because he habitually cruised at relatively high altitudes—a median of 11,500 feet msl and occasionally as high as Flight Level 180. These high cruise altitudes allowed him to achieve better than average cruise speeds (158 to 176 KTAS, median 165 KTAS) and achieve better than average fuel efficiency (9.5 to 13.4







Cash Back<sup>1</sup> Every Purchase A CASH BACK' REDEMPTION IS APPLIED AS A STATEMENT CREDIT. DUARTERLY BONUS POINT CAP OF 2 500 POINTS

Switch today to the AOPA World Mastercard<sup>®</sup>, and stop paying too much on your aviation purchases.

Visit AOPA.org/creditcard to learn more.



\*Certain points and purchases restrictions apply, see full Rewards Terms and Conditions for full details at AOPA.org/crediteard. 1. Rewards points can be redeemed for Cash Back or other items provided through AOPA Pilot Rewards. A Cash Back redemption is applied as a statement credit. The statement credit will reduce your balance but you are still required to make at least your minimum payment. A minimum of 2,500 points is needed to redeem for Cash Back. Values for non-cash back redemption items such as merchandise, gift cards, and travel may vary.



# Putting off your **PILOT'S LICENSE** or **INSTRUMENT RATING?**

Craving a SEAPLANE RATING?

Still paying for **ONE LESSON AT A TIME?** 

# APPLY NOW FOR AOPA'S FLEXIBLE AVIATION LOAN

## **DO YOU WANT QUICK & EASY?**

Fill out a quick online application and be approved in one business day.

## **DO YOU WANT AFFORDABLE?**

A \$10,000 flight training loan with monthly payments as low as \$250 a month. AOPA Member rates starting at WSJ Prime +5%.

## **DO YOU WANT FLEXIBILITY?**

You can borrow as much as 3x your monthly income (up to a max of \$100k).

# Go to aopa.org/financemytraining

to apply today.



**AOPA's Flexible Aviation Loan** can be put to work right now to get you on your way as a better trained, more proficient pilot.

# RUDDER & WRENCH

nautical miles per gallon, median 12 nm per gallon). Not too shabby.

#### Too hot in the climb

But, as Jack read further down his airplane's report card, he spotted something that got his attention.

0%	25%	50%	75%	100%
	354			iù.
			376	
300°F	348° F	363'F	378°F	450°F
WY SAYS				

The maximum CHT during the climb phase was uncomfortably warm: median 376 degrees Fahrenheit and maximum of 410 degrees Fahrenheit—way too hot for a Cirrus. The SR22 has an exceptionally efficient engine cooling system, and it's unusual to see CHTs much above about 360 degrees Fahrenheit in these airplanes. Jack's climb CHTs were unusual, and not in a good way.

The report card said diplomatically: "Your maximum CHTs have been higher than 75 percent of the cohort, higher than we like to see. We suggest you confirm that your full power fuel flow is adequate, ignition timing advance is correct, baffling is in good shape, and climb airspeed is high enough."

Jack's first thought was that he might have a problem with engine cooling baffles that were missing or mispositioned, a common cause of high CHTs. However, the section of the report card that showed maximum CHT spread in cruise made it clear that Jack's cooling system was in tiptop shape. The CHT spread measures the difference between the hottest and coolest CHT—the smaller the spread, the better. Jack's CHT spread was exceptionally tight, better than 69 percent of the cohort. So the problem must be something other than cooling baffles.

aximum CHT		spread between your l pread is an indication o finders.		
0%	25%	50%	75%	100%
	17		40)	-
0.001'F	24°F	30°F	39 ° F	150'F
AWY SAYS				
he median val-	e of the maximum	CHT spread during cru	ise flights is lower t	han 69% of



#### Not enough fuel flow


Another section of Jack's report card analyzed maximum fuel flow, which normally occurs during takeoff and initial climb. Sure enough, Jack's report card clearly showed that his maximum fuel flow was less than it ought to be:



Jack's median takeoff fuel flow was only 26.6 gallons per hour—a whopping 1.3 gph less than the cohort average of 27.9 gph. (Actually, we prefer to see takeoff fuel flow for these engines adjusted to 28 to 28.5 gph.) Jack's inadequate fuel flow could make a big difference in engine cooling during climb.

#### When did this start?

Jack hadn't really noticed these high CHTs in climb until he saw the report card. Naturally, he wondered how long this had been going on. To find out, he turned to his airplane's trend report that offers longitudinal analysis of critical parameters over time.



The trend report showed that the high climb CHTs had been going on for



97

# SAVE ON THE THINGS YOU NEED... AND THE THINGS YOU WANT

#### .....

#### ENJOY AOPA MEMBERS-ONLY DISCOUNTS ON:

- Avionics
- Hangars & Ground Equipment
- -Parts
- Pilot Supplies
- -Services
- Training
- Travel

## Start saving with AOPA today! aopa.org/lifestyles




### RUDDER & WRENCH

# Jack hadn't really noticed these high CHTs in climb until he saw the report card....The trend report showed that the high climb CHTs had been going on for months.

months. The highest recorded CHT of 410 degrees Fahrenheit (yikes!) took place in mid-June, and all the flights from mid-July to late August had CHTs that were uncomfortably hot. Starting in September, the CHTs started to decrease sharply—most likely correlated with the onset of cooler weather.

#### Another unwelcome trend

While looking at the trend report, another thing caught Jack's eye.



The report showed a statistically significant downtrend in takeoff rpm for Jack's airplane. Jack's Continental IO-550-N engine requires 2,700 rpm to achieve its maximum rated takeoff power of 310 horsepower. We start getting concerned if the airplane can't make at least 2,680 rpm. Jack's trend report showed that his takeoff rpm was around 2,660 in mid-June and drifted down to nearly 2,650 by mid-September—considerably out of tolerance and representing a loss of five to 10 horsepower.

Jack made a note to have his shop adjust the takeoff fuel flow to 28 to 28.5 gph and the propeller governor to 2,700 rpm during his next 50-hour maintenance.

#### Not just for leaning

You don't have to fly a Garminequipped Cirrus to take advantage of these report cards and trend reports. They're available to owners of nearly 200 airplane makes and models for which SavvyAnalysis has cohorts of meaningful size. You can find a complete list of supported make/model cohorts at apps.savvyaviation.com/ cohorts, and the list is growing weekly. The report cards and trend reports are sent out automatically on a regular basis, and can also be retrieved on demand at any time.

As Jack's experience shows, these reports can be incredibly useful in identifying mechanical and operational issues and spotting significant trends. The SavvyAnalysis platform accepts data from virtually all certified and experimental digital engine monitors that have recording capability. So, if you thought that your engine monitor was just for leaning, think again. • mike.busch@savvyaviation.com > savvyaviation.com

# Ask the A&Ps /

Mike Busch, Paul New, and Colleen Sterling answer your toughest aviation maintenance questions on our Ask the A&Ps podcast. Submit questions to podcasts@aopa.org. ▶ aopa.org/ask-the-a-and-ps

98 / AOPA PILOT / March 2022